944-SPEC - 944SPEC - low cost wheel to wheel racing Generated: 3 September, 2025, 20:58 Camshaft wear Posted by Manuel\_M - 09 Jan 2017 20:28 All the cams I've seen look like this. During a rebuild does anyone buy a new one or regrind to spec? \_\_\_\_\_\_ Re: Camshaft wear Posted by cbuzzetti - 09 Jan 2017 20:53 I am not sure I would use that one. I have never had to replace a cam shaft in a Spec car, so can't tell you much about it. Re: Camshaft wear Posted by Manuel\_M - 10 Jan 2017 05:52 This is just a stock photo from pelican, however I've seen maybe 6 and they all were the same. All used ebay ones seem to be the same also. Re: Camshaft wear Posted by Robbie - 20 Jan 2017 08:25 Every cam I've had looks like that too. Never checked the sizes, though.

Re: Camshaft wear

Posted by Manuel\_M - 20 Jan 2017 08:37

I've read somewhere "on the internet" that it is like that by design to help spin the lifter. Not sure if there is any truth to it, but the top of the lobes seem to not have wear.

-----