

Piston Skirt Wear

Posted by michaelreich - 09 Nov 2012 18:35

Quick question to you engine builders out there:

Measured bore and piston skirt diameter. The pistons/block are tolerance 1.

The bores are in spec and look really good. The piston skirts are 99.949 +/- less than .002mm across all pistons. The skirts are a bit shiny, but they do not look bad. Would you run them?

It looks like I am off about 0.034mm (against wear limit). I guess the taboo question is if I can get them coated (skirts only) to get them into spec if you do not think they will work.

Would appreciate any advice.

=====

Re: Piston Skirt Wear

Posted by Sterling Doc - 14 Nov 2012 16:02

He's the man!

=====