

## high comp pistons

Posted by rlofgren - 04 Jul 2008 06:32

---

i am trying to find the high compression pistons/88 motor setup for a new 944spec i am putting together. they do seem hard to come by. what i did come across was brand new exact replacement mahle pistons. are these legal for spec since they are same as stock? anyone have any experience with these?

[www.heritagemotorcar.com/research/piston.htm](http://www.heritagemotorcar.com/research/piston.htm)

=====

## Re:high comp pistons

Posted by JerryW - 04 Jul 2008 07:15

---

Hopefully you are not looking at the ones in the bottom picture ! We have enough problems keeping up with you -- the 968 Turbo would be a bit much !

=====

## Re:high comp pistons

Posted by norman#99 - 04 Jul 2008 07:41

---

There are 3 different tollerances, 0 - 1 - 2

It is very important that you have the correct pistons for your block, so you need to find out what block you have to know which pistons you need, I know of some that are for a 0 tolerance block.

=====

## Re:high comp pistons

Posted by rlofgren - 06 Jul 2008 05:51

---

are the 1 and 2 oversize for overboring/oversizing the cylinders? we can't do that with spec rules anyway. only problem is finding a used block with no wear on the bores cause we can't overbore.

=====

## Re:high comp pistons

Posted by Utah944 - 06 Jul 2008 07:58

---

Post a WTB on the pelican parts 944 used parts forums. Some of the guys want why too much for the parts but I have found some reasonable sellers. I have dealt with a parts above (not sure of the name) and he seems reasonable. if yo post what you are looking for you will receive responses.

=====

## Re:high comp pistons

Posted by SvoChuck - 06 Jul 2008 12:01

---

### **rlofgren wrote:**

are the 1 and 2 oversize for overboring/oversizing the cylinders? we can't do that with spec rules anyway. only problem is finding a used block with no wear on the bores cause we can't overbore.

the 1's and 2's are not overbores and are legal in 944-spec. I would guess they are .01 - .05 mm larger than a size "0". So maybe if you had some of these slightly larger pistons they would fit better in a block with some wear on it.

the overbore size is 100.5 vs 100 mm stock .

=====