

## Loose Stering Rod

Posted by 944cer - 21 Jul 2008 01:17

---

I just noticed some slopiness in one of the sterling rods. Is there a way to tighten this rod in the sterling unit? I have a power sterling rack that has been converted to manual (pump, resevoir removed and hose looped back to rack). The play appears to be at the rack and not the end links.

Thanks,

Lee

=====

## Re:Loose Stering Rod

Posted by 944cer - 22 Jul 2008 22:58

---

No worries. I get in touch with them.

Lee

=====