**944-SPEC - 944SPEC - low cost wheel to wheel racing** Generated: 4 September, 2025, 21:42

Loose Stering Rod osted by 944cer - 21 Jul 2008 01:17	
just noticed some slopiness in one of the stering rods. Is there a way to tighten this rod in nit? I have a power stering rack that has been converted to manual (pump, resevoir remo poped back to rack). The play appears to be at the rack and not the end links.	•
hanks,	
ee	
Re:Loose Stering Rod osted by 944cer - 22 Jul 2008 22:58	
lo worries. I get in touch with them.	
ee	